

Hygiene

collected in the work area. If into containers sited in a here they can be easily removed. ental safety regulations. rved: benches and floors must r spills. Used fixer must the processing area. to enable the technician to luge. The entire surface that no chemical spillage can

FIRST AID
 Accidental ingestion. If conscious, give plenty of water to drink. Do not induce vomiting.
 Eye irritation. Wash eyes with copious quantities of water for 15 minutes. If irritation persists, obtain medical advice.
 Accidental inhalation. If conscious, give plenty of water to drink. Do not induce vomiting.
 Skin irritation. Wash immediately with plenty of water. Do not use a neutral fluid (water) and neutralise or soothe if available.
 Accidental inhalation. If conscious, give plenty of water to drink. Do not induce vomiting.
 Eye irritation. Wash eyes with copious quantities of water for 15 minutes. If irritation persists, obtain medical advice.
 Accidental ingestion. If conscious, give plenty of water to drink. Do not induce vomiting.

ACTION
 TILATION SYSTEM PROVIDED
 OPERATE NIGHT & DAY,
 FRY OF FRESH AIR IN THE
 (15 AIR CHANGE PER HOUR)
 MUST BE DIRECTED TO THE
 SIDE OF BUILDING.
 HAVE EXHAUST SYSTEMS FITTED.
 TIED OVER ALL PROCESSORS.
 "FUME CAPBOARD"
 CHEMICALS - E.G.
 HYDRAZIDE.)

DETECTING THE DANGERS

- STRONG SMELL OF CHEMICALS IN WORKSPACE
- IMPROVE AIR INTAKE IMMEDIATELY
- ENSURE VENTILATION SYSTEM IS WORKING, -
 - LEAKING PROCESSOR, FAULTY DUCTING -
 OR BROKEN EXHAUST,
- SWITCH OFF MACHINE & CALL ENGINEER
- * DO NOT CONTINUE TO OPERATE PROCESSOR UNTIL FAULTS ARE RECTIFIED.

PHIC FILM PROCEDURES
 K PRACTICE
 OGRAPHERS
 RKROOM
 NICIANS

WARNING SIGNS
 IF THESE SYMPTOMS OCCUR AND PERSIST THEY SHOULD NOT BE IGNORED:
 RESPIRATORY TRACT: Nasal discharge, Catarrh, Sinus problems, Sinusitis
 NON RESPIRATORY: Sore eyes, Mouth ulcers, Tinnitus, Severe headaches, Hoarseness, Nausea, Chest pains, Extreme fatigue, Heart arrhythmia, Painful joints, loss of feeling in hands or feet.

YOUR HEALTH IS YOUR RESPONSIBILITY!
 • IF YOU OFTEN FEEL UNWELL AT WORK IN THE DARKROOM - REPORT TO YOUR SUPERVISOR.
 • YOU MAY BECOME ALLERGIC TO PROCESSING CHEMICALS.
 WORK RELATED ILLNESS IS PREVENTABLE IF WARNINGS ARE HEPPED.

